



To: All Simplex Distributors

Subject: Urgent Product Advisory Notice - Simplex Ratchet Jacks

Date: February 25, 2013

It has come to our attention that there is a potential quality issue with the amount of lubrication which is present in certain Ratchet Jacks which were manufactured during the date ranges outlined below.

This quality condition can result in excess wear and tear, binding, and possible failure of the Ratchet Jack, which could result in loss of the load being lifted. Such Ratchet Jack failure could result in potentially serious property damage and/or personal injury. A list of the Ratchet Jack model numbers which may be affected by this quality issue ("Target Model Numbers") is outlined below.

Target Model Numbers / Date Codes (production date range falls between April 2010 - February 2013)

Target Model Numbers		Affected Ratchet Jack Date Codes								
01040	RJ22B	A1003	A1005	A1102	A1103	A1104	A1105	A1201	A1202	A1203
01080	RJ24A	A1205	A1301	A1302	A1303	A1304	A1305	B1107	B1108	B1109
01130	RJ84A	B1110	B1205	B1206	B1207	B1208	B1209	C1011	C1012	C1013
1017	RJ85A	C1014	C1110	C1111	C1112	C1113	C1114	C1210	C1211	C1212
2029	RJ86A	C1213	D1015	D1016	D1017	D1018	D1114	D1115	D1116	D1117
22B	RJ1017	D1118	3 D1214	D1215	D1216	D1217	E1019	E1020	E1021	E1022
24A	RJ2029	E1023	E1119	E1120	E1121	E1122	E1123	E1218	E1219	E1220
320B	RJA1022	E122	E1222	F1023	F1024	F1025	F1026	F1027	F1123	F1124
321B	RJA1538	F1129	F1126	F1127	F1223	F1224	F1225	F1226	G1028	G1029
A1022	84AMC	G1030	G1031	G1128	G1129	G1130	G1131	G1227	G1228	G1229
A1029L	85AMC	G1230	G1231	H1032	H1033	H1034	H1035	H1036	H1132	H1133
A1029R	86AMC	H113	H1135	H1136	H1231	H1232	H1233	H1234	H1235	11036
A1538	A1022MC	11037	11038	11039	11040	11136	I1137	11138	I1139	11140
CR320B	1017MC	l1236	11237	11238	11239	J1041	J1042	J1043	J1044	J1141
CR321B	2029MC	J1142	J1143	J1144	J1145	J1241	J1242	J1243	J1244	K1045
CRA1029L	22BMC	K1046	K1047	K1048	K1049	K1145	K1146	K1147	K1148	K1149
CRA1029R	24AMC	K1245	K1246	K1247	K1248	L1049	L1050	L1051	L1052	L1053
		L1149	L1150	L1151	L1152	L1153	L1249	L1250	L1251	L1252

In the interest of safety, and to assure the highest possible quality standards, Simplex is asking you to <u>immediately</u> take the following measures:

Part 1: Distributor Stock Inspection / Lubrication Procedure:

Issue a "stop sale" on all inventories with any of the Target Model Numbers until they have passed the inspection guidelines per this Product Advisory. Locate the date code, which is printed on each unit's box and/or jack to determine which units, if any, fall within the production date range. If the date code falls within the outlined range, the unit should be quarantined until such time that you can perform the lubrication procedures attached to this Product Advisory. Once the proper lubrication procedures have been performed and the unit is functioning per the product guidelines, the unit can be returned to stock

and made available for immediate distribution. If the date code does not fall within the outlined range, then the unit can be returned to stock and made available for immediate distribution. Units which have already been inspected by Simplex and/or re-lubricated by Simplex, will have a green dot on the box label, near the date code. If you have units with a green dot, these units do not require any further action on your part.







Part 2: Contacting Your Customers:

Concurrent with the inspection of your inventory, immediately contact all customers to whom you have sold any of the Target Ratchet Jack Model Numbers between April 2010 and February 2013 to alert them of this Product Advisory. To assist you in contacting your customers, we have created a Customer Product Advisory in the form of a postcard.

The postcards direct your customers how to respond to this Product Advisory and also remind them that all Ratchet Jacks should be inspected before each use and immediately removed from service if any parts appear worn, bent, rusted or otherwise damaged. Proper maintenance and lubrication procedures are outlined in the Ratchet Jack Operational Manual, document # 87091, revision B. A current copy of the Operation Manual, as well as step-by-step lubrication instructions can be downloaded off the web at www.tksimplex.com/mechanical field advisory.pdf.

To assist you in contacting your customers about this Product Advisory, you have two options:

1). Simplex Performs the Product Advisory Mailing:

O You will provide the Simplex Customer Service Department a list of customer addresses in a Microsoft Office EXCEL® format. Upon receipt, Simplex will mail the Product Advisory Postcard to your customers. This list will be held confidential and will not be used for any other purposes. Email your customer list to info@tksimplex.com.

2). Distributor Performs the Product Advisory Mailing:

 Contact Simplex Customer Service by phone (Inside U.S. 1-800-323-9114, Outside U.S. 1-630-590-6990) or email (info@tksimplex.com), and request the quantity of Product Advisory Prepaid Postcards required.
 Once received, you are responsible for affixing the customer address labels and mailing them to your customers.

We want to thank all of you in advance for your help in ensuring that Simplex customers continue to receive the high quality products they have grown to expect.

If you have any additional questions regarding this Product Advisory, please feel free to contact Simplex Customer Service by phone (Inside U.S. 1-800-323-9114, Outside U.S. 1-630-590-6990) or email (info@tksimplex.com).

full F. Dutan

Our "Global Limited Lifetime Warranty" coverage will not be affected.

Sincerely,

Aaron Sztuk Marketing Leader Arnold Decker Chief Engineer Chris David Quality Leader



THIS IS A SAMPLE OF THE POSTCARD THAT YOUR CUSTOMERS WILL RECEIVE

PLEASE REFER TO "PART 2: CONTACTING YOUR CUSTOMERS" IN THE DISTRIBUTOR LETTER FOR INFORMATION ON HOW TO ORDER THIS POSTCARD FROM OUR CUSTOMER SERVICE DEPARTMENT.



URGENT PRODUCT ADVISORY: SIMPLEX RATCHET JACKS

Product Advisory Model Numbers and Date Codes Provided

Contact Simplex Customer Service by phone (Inside U.S. 1-800-323-9114, Outside U.S. 1-630-590-6990, Fax 1-630-590-6955) or email (info@tksimplex.com) to answer any specific questions about this Product Advisory.

www.tksimplex.com


777 Oakmont Lane, Ste. 800, Westmont, IL 60559 Inside U.S. 1-800-323-9114 • Outside U.S. 1-630-590-6990

URGENT PRODUCT ADVISORY: SIMPLEX RATCHET JACKS

If you have a Simplex Ratchet Jack, failure to comply with this Product Advisory could result in potentially serious property damage and/or personal injury.

Quality Issue:

This notification is to make you aware of a potential quality issue regarding the amount of lubrication which is present in certain Ratchet Jacks which were manufactured during the date ranges set forth on the bottom of this postcard. This quality condition can result in excess wear and tear, binding, and possible failure of the Ratchet Jack, which could result in loss of the load being lifted. Such Ratchet Jack failure could result in potentially serious property damage and/or personal injury. A list of the Ratchet Jack model numbers which may be affected by this quality issue is set forth on the bottom of this postcard.





Immediate Action to be Taken:

- If you believe that you have a Ratchet Jack with a Model Number and affected Date Code listed on the bottom
 of this postcard, immediately stop using the Ratchet Jack and visit www.tksimplex.com/mechanical field
 advisory.pdf to download complete instructions and details on how to ensure that your unit is properly lubricated.
- Irrespective of whether or not your Ratchet Jack is subject to this Product Advisory, please remember to always inspect your Ratchet Jack before use and immediately remove it from service if any parts appear worn, bent, rusted or otherwise damaged.
- Visit www.tksimplex.com to locate your nearest Simplex Authorized Service Center or contact Simplex
 Customer Service by phone (Inside U.S. 1-800-323-9114, Outside U.S. 1-630-590-6990, Fax 1-630-590-6955) or
 email (Info@tksimplex.com) to answer any questions you have about this Product Advisory or how to properly care
 for and maintain your Ratchet Jack.

URGENT PRODUCT ADVISORY: SIMPLEX RATCHET JACKS

Ratchet Jack Model Numbers:		Affected Ratchet Jack Date Codes:								
01040	RJ24A	A1003	A1005	A1102	A1103	A1104	A1105	A1201	A1202	A1203
01080	RJ84A	A1205	A1301	A1302	A1303	A1304	A1305	B1107	B1108	B1109
01130	RJ85A	B1110	B1205	B1206	B1207	B1208	B1209	C1011	C1012	C1013
1017	RJ86A	C1014	C1110	C1111	C1112	C1113	C1114	C1210	C1211	C1212
2029	RJ1017	C1213	D1015	D1016	D1017	D1018	D1114	D1115	D1116	D1117
22B	RJ2029	D1118	D1214	D1215	D1216	D1217	E1019	E1020	E1021	E1022
24A	RJA1022	E1023	E1119	E1120	E1121	E1122	E1123	E1218	E1219	E1220
320B	RJA1538	E1221	E1222	F1023	F1024	F1025	F1026	F1027	F1123	F1124
321B	84AMC	F1125	F1126	F1127	F1223	F1224	F1225	F1226	G1028	G1029
A1022	85AMC	G1030	G1031	G1128	G1129	G1130	G1131	G1227	G1228	G1229
A1029L	86AMC	G1230	G1231	H1032	H1033	H1034	H1035	H1036	H1132	H1133
A1029R	A1022MC	H1134	H1135	H1136	H1231	H1232	H1233	H1234	H1235	11036
A1538	1017MC	11037	11038	11039	11040	11136	11137	11138	11139	11140
CR320B	2029MC	11236	11237	11238	11239	J1041	J1042	J1043	J1044	J1141
CR321B	22BMC	J1142	J1143	J1144	J1145	J1241	J1242	J1243	J1244	K1045
CRA1029L	24AMC	K1046	K1047	K1048	K1049	K1145	K1146	K1147	K1148	K1149
CRA1029R		K1245	K1246	K1247	K1248	L1049	L1050	L1051	L1052	L1053
RJ22B	:	L1149	L1150	L1151	L1152	L1153	L1249	L1250	L1251	L1252

URGENT PRODUCT ADVISORY: SIMPLEX RATCHET JACKS

Contact Simplex Customer Service by phone (Inside U.S. 1-800-323-9114, Outside U.S. 1-630-590-6990, Fax 1-630-590-6955) or email (<u>info@tksimplex.com</u>) to answer any specific questions about this Product Advisory.



URGENT PRODUCT ADVISORY: SIMPLEX RATCHET JACK LUBRICATION PROCEDURE FOR ALL MODELS

Equipment Needed:

- * Needle Nose Pliers
- * SAE 20 wt. Oil
- * Oil Can/Dispenser
- * Graphite Grease
- * Grease Applicator



Estimated Time To Complete Procedure:

Approximately 5 - 7 Minutes.

Step 1 - Unbox, if applicable:

Perform this procedure with the jack in the upright position.



Step 2 - Remove Side Access Door:

Using needle nose pliers, carefully straighten the cotter pin, and remove to gain access to the internal mechanism. Set aside for reinstallation later.







Step 3 - Lubricate Lifting Pawl and Trunnion Bearings:

If lubrication is visually present, proceed to Step 4.

If lubrication is <u>not</u> visually present, apply 6 drops of SAE 20 weight (WT.) oil into all of the pivoting areas within the jack; see oiling areas to the right. It's recommended to operate the handle socket to ensure oil penetration in-between the pivot points. Proceed to Step 4.








Step 4 - Lubricate Rack Bar:

With the reversing lever up, grasp the load cap and manually pull the rack bar out until it mechanically stops.







Step 4 - Lubricate Rack Bar continued:

If lubrication is **visually present**, shift the reversing lever down and lower the rack bar by operating the handle socket until the rack bar mechanically stops, Proceed to Step 5.





If lubrication is **not visually present**, carefully apply graphite grease to the face side opposite of the teeth, coating the surface entirely, but **not applying any grease onto the teeth**. Once complete, shift the reversing lever down and operate the handle socket until the rack bar mechanically stops. Proceed to Step 5.







Step 5 - Lubricate Spring Link Assembly and Retaining Pawl:

Lubricate the spring link assembly by applying graphite grease on the springs ensuring a uniform coating.

Lubricate the retaining pawl pin by applying 6 drops of SAE 20 weight (WT.)





Step 6 - Functional Check:

Place one hand on lifting toe and operate the handle socket to move the rack bar several teeth in both directions, changing the reversing lever position will determine stroke movement. Verify that the teeth properly mesh into the rack bar, no unusual drag during movement and an audible clicking noise is present during operation. If not, have the jack inspected by an Authorized Service Center. Visit www.tksimplex.com to locate the nearest one.





Step 7 - Reinstall Side Access Door:

Carefully reinstall the side access door, and insert the cotter pin. Using needle nose pliers, carefully bend one ear 90 degrees to secure cotter pin.



The lubrication procedure is complete, place ratchet jack back into the packaging material, and place an "X" on the box label near the date code indicating the product is available for distribution.

