



STIHL Incorporated • P.O. Box 2015 • Virginia Beach, Virginia 23450-2015 U.S.A. • www.stihlusa.com

536 Viking Drive
Virginia Beach, Virginia 23452
Telephone: (757) 486-9100
Fax: (757) 631-5745

July 25, 2019

To: STIHL Dealers Who Have Purchased STIHL Polycut™ 27-3 and STIHL Polycut™ 47-3 Trimmer Heads

Subject: Stop Sales of All STIHL Polycut™ 27-3 and STIHL Polycut™ 47-3 Trimmer Heads and Components

Attention STIHL Dealer,

Effective immediately, please discontinue selling all STIHL Polycut™ 27-3 and STIHL Polycut™ 47-3 trimmer heads and accessory parts for these heads. The part numbers involved are listed below:

STIHL Polycut™ 27-3 trimmer head part no. 4002 710 2176

STIHL Polycut™ 47-3 trimmer head part no. 4003 710 2117

STIHL Polycut™ Blade Kit part no. 4002 007 1000

(for Polycut™ 7-3 use replacement blades part no. 4111 007 1001 as a substitute)

4002 710 9700 Base

4003 007 1000 Deflector Kit

This notice pertains only to the STIHL Polycut™ 27-3 and STIHL Polycut™ 47-3 trimmer heads and the part numbers listed above. An example of the STIHL Polycut™ 27-3 is shown in the photos below. No other trimmer or brushcutter cutting heads or attachments are involved in this notice.



Further information and instructions will be communicated once more details become available.

If you have any questions, please contact your STIHL Distributor or Branch Service Center for information.

We apologize for the inconvenience.