

IMPORTANT SAFETY RECALL

DEWALT Model DWS779, DWS780 and DHS790 Miter Saws

Plastic rear guard assembly can break/shatter when struck, exposing the saw blade and posing a laceration hazard.

The following miter saw models are affected:


DEWALT Model DWS779, DWS780 and DHS790 (designated DHS790AB or DHS790AT2 on the carton)

Only date codes 2019 04 through 2022 04 are affected.

The date code (20XX YY-ZZ) information is as follows:

20XX = year, YY = week, ZZ = plant code (either CJ or 49)

If your saw does not have a date code or you cannot locate it, please contact us.



If the saw is marked with green or black dots as indicated in either of these two locations, it has already been inspected and is not affected.



If your saw is affected, STOP USING IT IMMEDIATELY and contact DEWALT to obtain a free repair kit using any of these options:

1. Go to: <https://www.dewalt.com/miter-saw-recall>
2. Scan this QR code on the right:
3. Call toll free 1-800-990-6421 between 8 a.m. and 6 p.m., Eastern Time, M-F



**SCAN HERE
TO GET A
FREE
REPAIR KIT**